


MONUMENT RECORD


STATE OF INDIANA ~ COUNTY OF MONROE

Section 10, Township 9 North, Range 1 West,Monument Description & Remarks: 3/4" Iron Pipe found 0.5' above groundCOMPLETED By Steve Farber

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E. Bledsoe

Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD
State of Indiana - County of Monroe

Section: 10

Township: 9 North

Range: 1 West

Corner ID: Blm Q-07


Monument Description & Remarks: Found 3/4" Iron Pipe at East 1/4 corner of section. Iron Pipe was approximately 6" out of ground and marked with many layers of pink and orange flagging. Current property owner had survey by Edmund Farkas, dated April 4, 1983 which referenced the iron pipe as the corner.

References On File: Survey plat by Gary Cobb, R.L.S. No S0377 (Bloomington Engineering Co.), dated May 2, 1995; recorded in Book 3, Page 403 in the County Recorder's Office.


RECOVERY TIE DRAWING

Field Book 99-01 Page No. 70

USGS Bloomington Quad



- A - 3/4" Iron Pipe
- B - North 33° East, 23.65' from pipe
MAG nail in 12" cluster Red Oak
- C - South 86° East, 10.61' from pipe
MAG nail in 6" Beech
Survey marker sign set 4' up
- D - South 36° East, 14.00' from pipe
MAG nail in 5" Beech




Not To Scale

Compass Bearing Magnetic North

Note: 5/8" rebar with "Graham" cap just south of Old Myers Rd. (see drawing above)

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36 of the Indiana Code; and the above data is given under my hand and seal this 23rd day of November, 1999.



Administered by the Monroe County Surveyor Review Board



Date: December 2, 1999